

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL-67S95W /28NWSW

Location ID: 334071



Photo #5045 from entrance to location.



Photo #5046 from entrance to location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC S. PARACHUTE FEDERAL-67S95W /28NWSW

Location ID: 334071



Photo #5047 No battery sign located at the tank battery.



Photo #5048 Glycol storage tank missing required information.

