

Caerus Piceance LLC
Piceance unit 296-6B
Location # 413466



location



location



Caerus Piceance LLC
Piceance unit 296-6B
Location # 413466



location



location



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
Piceance unit 296-6B
Location # 413466



Open cellar



Open cellar



Caerus Piceance LLC
Piceance unit 296-6B
Location # 413466



Debris



Debris



Caerus Piceance LLC
Piceance unit 296-6B
Location # 413466



Lack of stabilization/erosion



Lack of stabilization/erosion



Caerus Piceance LLC
Piceance unit 296-6B
Location # 413466



Lack of stabilization/erosion



Lack of stabilization/erosion

