

Inspection Photos

10/08/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 324061

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324061



October 8, 2021



October 8, 2021
39.45485719N 107.83379805W

Photo 1: Photos show bird protection devices are missing from the two northern most separators on the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324061



October 8, 2021
39.45494287N 107.83342185W



October 8, 2021
39.45501573N 107.83352691W

Photo 2: Photos taken from the eastern interim areas of the Location. Though areas are progressing towards 1003 standards, biennial species such as *Melilotus officinalis* were observed to be the dominant plant established on the eastern interim areas.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324061



October 8, 2021



October 8, 2021
39.45458611N 107.83423193W

Photo 3: Photos taken from the western interim areas of the Location. Photo shows noxious weeds (Musk thistle). Photos also show areas that are dominated by undesirable plant species such as mustard and cheat grass that can hinder reclamation.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 324061



Photo 4: Additional photos taken from the western interim areas showing musk thistle rosettes.