

Inspection Photos

10/08/2021

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323866

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323866



Photo 1: Photos taken from the interim areas of the Location. Photo shows example of Undesirable and Noxious plant species observed on the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 323866



October 8, 2021
39.45854273N 107.8325896W



October 8, 2021
39.45854644N 107.83264387W

Photo 2: Photos taken from the western interim areas of the Location. Photo shows interim areas that are not progressing towards a uniform, desirable vegetative standard in accordance with 1003 rules; erosion evident in bare areas. Additional reclamation efforts required in these areas.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location ID: 323866



Photo 3: Photos taken from the northwestern end of the Location. Photo shows the stormwater diversion ditch on the wester perimeter of the Location has not been constructed in accordance with good engineering practices; ditch not constructed with an appropriate outlet; runoff from the ditch is causing erosion degradation on the north end of the Location.