

Inspection Photos

10/08/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 334685

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334685



October 8, 2021
39.46605564N 107.83312186W



October 8, 2021
39.466052N 107.8331297W

Photo 1: Photo taken from the west end of the Location. Photos 1-2 provide an overview of the Location from north, northeast, southeast to south.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334685



October 8, 2021
39.46605049N 107.83312935W



October 8, 2021
39.4660528N 107.83313009W

Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334685



October 8, 2021
39.46606802N 107.83268304W



October 8, 2021
39.4660111N 107.83266004W

Photo 3: Photo shows bird protection screen is missing from the separator equipment.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334685



Photo 4: Photo taken from the eastern interim areas of the Location. Photo provides example showing interim areas are stabilize, and progressing towards 1003 standards; no imminent or immediate stormwater concerns were observed at time of inspection.