

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOOAGLUND-67S95W /2NWNW

Location ID: 334724



Photo #5057 from entrance to location.



Photo #5058 from entrance to location.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC HOOAGLUND-67S95W /2NWNW

Location ID: 334724



**Photo #5059 Glycol storage tank missing required information.**