

# Inspection Photos

10/13/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 334613

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334613



**Photo 1:** Photos 1-2 provide an overview from the east end of the Location facing south, southwest, northwest to north.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334613



**Photo 2:** See comments under photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334613



**Photo 3:** Photos taken from eastern interim areas of the Location; photos provide example of the observed reclamation. It is noted that though interim areas of the Location have achieved a uniform perennial vegetative establishment, species observed established on the interim areas of the Location are predominantly introduced, and not reflective of the reference area,



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334613



October 13, 2021  
39.41443506N 107.72893579W

**Photo 4:** Photo taken from the tank battery. Photo shows unused stock tank stored within the secondary containment of the batter. Equipment is unused and requires removal.

