

Inspection Photos
Location Name: Nelson 17-44-9-60
Location ID: 422744



Photo 1 – Pumping Units



Photo 2 – 1-20-9-60 Wellhead – Stained Soil

Inspection Photos
Location Name: Nelson 17-44-9-60
Location ID: 422744



Photo 3 – Unused Rods and Tubing at 1-20-9-60



Photo 4 – Heater Treater

Inspection Photos
Location Name: Nelson 17-44-9-60
Location ID: 422744



Photo 5 – Tank Battery



Photo 6 – Tank Battery Sign



Inspection Photos
Location Name: Nelson 17-44-9-60
Location ID: 422744



Photo 7 – Heater Treater and ECD