

**Inspection Photos**  
**Operator: Kinder Morgan**  
**API: 033-06078**  
**Date: 10/11/2021**



Photo 1. View of well pad from entrance facing center.



Photo 2. View of well pad cut-slopes. Per conditions of approval on variance. Slopes need to be reduced to a maximum of 3:1. This work is not conducted.



Photo 3. View of variance area from the southwestern corner facing center.



Photo 4. View of project area from the southeastern corner facing center.



Photo 5. View of reference area comprised of mixed pinyon/juniper, serviceberry and gambel oak shrubland. With understory of prickly pear, Indian ricegrass, rock goldenrod, and James galleta.