

Inspection Photos
Operator: Kinder Morgan
API: 033-06134
Date: 10/11/2021



Photo 1. View of project area from the well pad entrance facing center. Per onsite communication with operator, frac tank parked on the well pad is placed by cattle operator to supply water to cows.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing, largely with western wheatgrass.



Photo 3. View of the northern project area from the northern project area and western project area (in background), facing westward.



Photo 4. View of reference area comprised of Ponderosa pine woodland with serviceberry and gambel oak shrubland, and an understory of black sage, western wheatgrass, and James galleta.