

Inspection Photos

Location Name: RIVER RANCH A PAD

Location ID: 336014 & Spill/Release ID: 480927

Inspection Date: October 12, 2021



Location sign.





Inspection Photos
Location Name: RIVER RANCH A PAD
Location ID: 336014
Spill/Release ID: 480927
Inspection Date: October 12, 2021

Spill/release point looking south,
note the 10-inch produced water
poly line riser and the marshy area
in the background.

Oct 12, 2021 1:54:48
39.53859611N 107.6976
Altitude:162
Speed:3.0k





Inspection Photos
Location Name: RIVER RANCH A PAD
Location ID: 336014
Spill/Release ID: 480927
Inspection Date: October 12, 2021

Spill/release point looking northwest towards the RIVER RANCH A PAD tank battery. Note what appeared to be storm water comingled with paraffin around the 10-inch produced water poly line riser.

Oct 12, 2021 2:10:59
39.53849166N 107.697629
Altitude:1621
Speed:0.0k





Inspection Photos
Location Name: RIVER RANCH A PAD
Location ID: 336014
Spill/Release ID: 480927
Inspection Date: October 12, 2021

Spill/release point looking northeast, note the 10-inch produced water poly line riser, the marshy area in the background and the boom (blue) located in the foreground.

Oct 12, 2021 2:06:40
39.53848618N 107.697787W
Altitude:1620
Speed:0.0k





Oct 12, 2021 2:05:50
39.53845959N 107.697814
Altitude: 1618
Speed: 0.0k

Inspection Photos
Location Name: RIVER RANCH A PAD
Location ID: 336014
Spill/Release ID: 480927
Inspection Date: October 12, 2021

Paraffin that was observed around the spill/release point. A detectable hydrocarbon odor was present at time of inspection.



Oct 12, 2021 2:03:01
39.53837907N 107.697887W
Altitude: 1617
Speed: 0.0k

Inspection Photos
Location Name: RIVER RANCH A PAD
Location ID: 336014
Spill/Release ID: 480927
Inspection Date: October 12, 2021

Access to the marshy area located southwest of the spill/release point. Note the tire ruts, hose and bucket.





Oct 12, 2021 2:03:16
39.53835497N 107.697805
Altitude: 1616
Speed: 3.2k

Inspection Photos
Location Name: RIVER RANCH A PAD
Location ID: 336014
Spill/Release ID: 480927
Inspection Date: October 12, 2021

Access to the marshy area located southwest of the spill/release point. Note the hose and the surface water in the background.





Inspection Photos
Location Name: RIVER RANCH A PAD
Location ID: 336014
Spill/Release ID: 480927
Inspection Date: October 12, 2021

Marshy area located southwest of the spill/release point. Note the hose and the paraffin that is spread throughout the vegetation.

Oct 12, 2021 2:03:39
39.53833037N 107.697774
Altitude: 1616
Speed: 0.0k





Oct 12, 2021 2:03:36
39.53832968N 107.697769
Altitude:1616
Speed:0.0k

Inspection Photos
Location Name: RIVER RANCH A PAD
Location ID: 336014
Spill/Release ID: 480927
Inspection Date: October 12, 2021

Marshy area located southwest of the spill/release point. Note the hose and the paraffin that is spread throughout the vegetation.





Oct 12, 2021 1:59:45
39.53829916N 107.697762
Altitude:1619
Speed:0.0k

Inspection Photos
Location Name: RIVER RANCH A PAD
Location ID: 336014
Spill/Release ID: 480927
Inspection Date: October 12, 2021

Marshy area located southwest of the spill/release point. Note the hose and the paraffin that is spread throughout the vegetation.





Oct 12, 2021 2:02:04
39.53828906N 107.697764
Altitude: 1618
Speed: 0.7k

Inspection Photos
Location Name: RIVER RANCH A PAD
Location ID: 336014
Spill/Release ID: 480927
Inspection Date: October 12, 2021

Marshy area located southwest of the spill/release point. Note paraffin that is spread throughout the vegetation.





Inspection Photos

Location Name: RIVER RANCH A PAD

Location ID: 336014

Spill/Release ID: 480927

Inspection Date: October 12, 2021

Marshy area located southwest of the spill/release point. Note the hose and the hydrocarbon sheen present on the surface water.

Oct 12, 2021 2:00:00
39.5383058N 107.697758W
Altitude: 1618
Speed: 0.0k



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources



Inspection Photos
Location Name: RIVER RANCH A PAD
Location ID: 336014
Spill/Release ID: 480927
Inspection Date: October 12, 2021

Spill/Release point looking southeast, note the 10-inch produced water poly line riser and the marshy area in the background.

Oct 12, 2021 2:08:04
39.5385617N 107.697709W
Altitude: 1619
Speed: 1.7k





Inspection Photos
Location Name: RIVER RANCH A PAD
Location ID: 336014
Spill/Release ID: 480927
Inspection Date: October 12, 2021

**Marshy area located southeast of
the spill/release point.**

Oct 12, 2021 2:08:36
39.53845397N 107.697544
Altitude:162
Speed:0.0k





Inspection Photos

Location Name: RIVER RANCH A PAD

Location ID: 336014

Spill/Release ID: 480927

Inspection Date: October 12, 2021

Marshy area located southeast of the spill/release point. Note the paraffin on the surface water and vegetation.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources