

Inspection Photos
Location Name: Sandie 43-12
Location ID: 320037

Oct 11, 2021 at 1:07:05 PM
39.975627,-104.490001
Keenesburg CO 80643
United States
COGCC



Pic 1 tank, unused propane tank on trailer, weeds unmanaged,

Oct 11, 2021 at 1:07:23 PM
39.975627,-104.490001
Keenesburg CO 80643
United States
COGCC



Pic 2 separator, weeds unmanaged


Inspection Photos
Location Name: Sandie 43-12
Location ID: 320037

Oct 11, 2021 at 1:07:44 PM
39.975706,-104.489916
Keenesburg CO 80643
United States
COGCC



Pic 3 Gas meter run, oil tanks, weeds on location unmanaged

Oct 11, 2021 at 1:09:25 PM
39.975664,-104.492228
Keenesburg CO 80643
United States
COGCC



Pic 4 Pump jack, wire rope on pumping unit bridle appears to have parted, polish rod is bent.