

**Inspection Photos**  
**Location Name: Abbott 12-21**  
**Location ID: 320477**

Oct 11, 2021 at 3:46:30 PM  
39.975533,-104.471739  
3450 E 160th Ave  
Greeensburg CO 80643  
United States  
COGCC



**Pic 1 Tanks, weeds unmanaged**

Oct 11, 2021 at 3:46:45 PM  
39.975533,-104.471739  
3450 E 160th Ave  
Greeensburg CO 80643  
United States  
COGCC



**Pic 2 trash, stained soil next to tanks**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: Abbott 12-21**  
**Location ID: 320477**

Oct 11, 2021 at 3:46:59 PM  
39.975533,-104.471739  
3450 E 160th Ave  
Greeensburg CO 80643  
United States  
COGCC



**Pic 3 gas meter run, vertical separator, ECD**

Oct 11, 2021 at 3:47:53 PM  
39.947934,-104.451044  
COGCC



**Pic 4 unused separator near wellhead, weeds unmanaged.**



**Inspection Photos**  
**Location Name: Abbott 12-21**  
**Location ID: 320477**

Oct 11, 2021 at 3:48:14 PM  
39.946760,-104.450219  
Bennett CO 80102  
United States  
COGCC



**Pic 5 wellhead, weeds unmanaged on location**

Oct 11, 2021 at 3:49:47 PM  
39.947491,-104.450403  
COGCC



**Pic 6 open top tank, unable to visually inspect due to weed growth on location**