

Caerus Piceance LLC  
L34  
Location # 334916



Location



location

Caerus Piceance LLC  
L34  
Location # 334916



Location



location/lack of battery signage





Caerus Piceance LLC  
L34  
Location # 334916



Follow up inspection photo



Previous inspection photo



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Caerus Piceance LLC  
L34  
Location # 334916



Previous inspection photo



Follow up inspection photo



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Caerus Piceance LLC  
L34  
Location # 334916



Follow up inspection photo



Lack of labeling

