

Caerus Piceance LLC
P33NE
Location # 334857



Location



location

Caerus Piceance LLC
P33NE
Location # 334857



Location/lack of battery signage



Lack of labeling

Caerus Piceance LLC
P33NE
Location # 334857



Previous inspection photo



Follow up inspection photo

Caerus Piceance LLC
P33NE
Location # 334857



Previous inspection photo



Follow up inspection photo

Caerus Piceance LLC
P33NE
Location # 334857

Mar 9, 2021 at 10:31:20 AM
39.478685,-107.664222 ±4.78m
COGCC



Previous inspection photo



Oct 14, 2021 at 11:33:15 AM
+39.478784,-107.664199 ±4.76m
COGCC

Follow up inspection photo