

Inspection Photos

10/13/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 334271

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334271



October 13, 2021
39.41200713N 107.7001888W



October 13, 2021
39.41220374N 107.70070328W

Photo 1: Photos show example of vegetative establishment on the interim areas of the Location; though the species observed established on the interim areas of the Location are predominantly introduced, and not reflective of the reference area, interim areas of the Location have achieved a uniform perennial vegetative establishment

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 334271



October 13, 2021
39.41218037N 107.7003671W



October 13, 2021
39.41218721N 107.70061027W

Photo 2: Photo left shows example of marked anchors observed on the Location. Photo on right shows production areas; control measures to stabilize production areas during wet conditions show signs of degrading; advise maintenance prior to BMP failure.