

# Inspection Photos

10/13/2021

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 334156

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334156



**Photo 1:** Photos show example of vegetative establishment on the interim areas of the Location; vegetation observed predominantly undesirable weedy plant species, however desirable plant establishment was observed under weeds. Weed management advised to facilitate interim areas progress towards 1003 standards.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334156



**Photo 2:** Photos taken from the soil stockpiles on the west end of the Location. Photo shows slopes remains predominantly bare and exposed soil; BMPs to protect soils from erosion degradation observed to be missing or insufficient. Areas are not progressing towards 1003 standards; additional reclamation activities required.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334156



**Photo 3:** Photos taken from the sediment trap/pond on the south end of the Location. Photo shows control measures has not been not been constructed in accordance with good engineering practices or maintained in a proper functioning condition; BMP constructed with steep slopes with inadequate protection to prevent erosion degradation; BMP has not been constructed with an appropriate inlet; slopes around inlet and edge of pad insufficiently stabilize; erosion degradation evident.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334156



**Photo 4:** See comments under photo 3.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 334156



**Photo 5:** Photo shows bird protection devices are missing from the western separator unit on the Location.