

Inspection Photos
Location Name: David Howard #3
Location ID: 317904



Photo 1 loc pic Debris : dead weeds on road and around well site

Photo 2 Debris: dead weeds around location.

Inspection Photos
Location Name: David Howard #3
Location ID: 317904



Photo 3 Debris: dead weeds around location and electric panel.