

Inspection Photos
Location Name: David Howard unit C#2
Location ID: 319232



Photo 1 well head and Debris: dead weeds on and around location.



Photo 2 Debris: dead weeds in and along road access.