

Inspection Photos  
Location Name: Husky Unit B 1  
API # : 033-06008



Well sign – no valid 24-hour operator contact number

Inspection Photos  
Location Name: Husky Unit B1  
API #: 033-06088



**Bradenehead plumbed to surface**

Inspection Photos  
Location Name: Husky Unit B 1  
API #: 033-06008



No gas meter calibration record visible



Lube oil accumulating