

Final Reclamation Inspection

September 17th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 326978

Inspection Document #: 701900121

Weld County, CO

NESW Section 10 T6N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Avery 23-10
Location ID: 326978



Photo 1. 2021 aerial imagery of the well pad and access road (north is up). The tank battery (highlighted in blue) remains and will be associated with shut in well API # 123-20241.

Inspection Photos
Location Name: Avery 23-10
Location ID: 326978




Photo 2. Well pad and reference overview photo taken using a drone (north is right).
Photo shows the well pad appears consistent with the reference area.

Inspection Photos
Location Name:Avery 23-10
Location ID: 326978



Photo 3. Ground photo taken from the southern end of the well pad looking north up the access road.