

# Inspection Photos

API: 043-06142

Operator: JAVERNICK OIL

Inspection Date: 10/15/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 043-06142 | Date: 10/15/2021

## Inspection Photos



**Photo 1.** Drone aerial photo facing east toward the abandoned well site. The trailer is still parked on the well site shown at red arrow. The disturbance area circled consists of mostly undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06142 | Date: 10/15/2021



## Inspection Photos



**Photo 2.** Facing southwest toward the location. Trailer remains in the same position as observed in previous inspection last year.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06142 | Date: 10/15/2021



## Inspection Photos



**Photo 3.** Facing west toward the location which consists of undesirable weeds (Kochia, Russian thistle).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06142 | Date: 10/15/2021



## Inspection Photos



**Photo 4.** View of ground cover shows undesirable weeds observed throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06142 | Date: 10/15/2021



## Inspection Photos



**Photo 5.** Facing southeast. This is where soil pile was previously observed which has been removed. This area has not been reclaimed and is susceptible to erosion.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06142 | Date: 10/15/2021



## Inspection Photos



**Photo 6.** The cable previously observed still remains at east side of location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06142 | Date: 10/15/2021



## Inspection Photos



**Photo 7.** Center of the location facing west. The location has not been reclaimed and consists of undesirable weeds.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06142 | Date: 10/15/2021



## Inspection Photos



**Photo 8.** Facing north toward the surrounding undisturbed reference area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 043-06142 | Date: 10/15/2021