

Inspection Photos

API: 043-06141

Operator: JAVERNICK OIL

Inspection Date: 10/15/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-06141 | Date: 10/15/2021

Inspection Photos



Photo 1. Drone aerial photo facing west toward the well site. There is various unused equipment stored on the location which needs to be removed. Most of the equipment was observed in the same position during the previous inspection last year.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06141 | Date: 10/15/2021

Inspection Photos



Photo 2. Drone aerial photo facing north toward the well site. There is various unused equipment stored on the location which needs to be removed. Most of the equipment was observed in the same position during the previous inspection last year.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06141 | Date: 10/15/2021

Inspection Photos



Photo 3. Facing west at the well site. The pumpjack has been disconnected from the well. The well is shown at red arrow. The well appears to be temporarily abandoned.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06141 | Date: 10/15/2021

Inspection Photos



Photo 4&5. There are buckets of oily substance which has spilled over and are not covered/sealed.



Inspection Photos



Photo 6. Facing southwest toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06141 | Date: 10/15/2021

Inspection Photos



Photo 7. Facing west at the south side of the location. There is various unused equipment stored on location which needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06141 | Date: 10/15/2021

Inspection Photos



Photo 8&9. Facing toward the well which is located at red arrow.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API: 043-06141 | Date: 10/15/2021

Inspection Photos



Photo 10. Facing northwest at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06141 | Date: 10/15/2021

Inspection Photos



Photo 11. Facing southwest at the location. All used equipment needs to be removed. Well is located at red arrow under the trailer.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06141 | Date: 10/15/2021