

Final Reclamation Inspection

September 22nd, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 322556

Inspection Document #: 701900133

Weld County, CO

NWSW Section 27 T6N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Koehler Frank 13-27
Location ID: 322556




Photo 1. 2019 aerial imagery of the tank battery, well pad and associated access road (north is up).

Inspection Photos
Location Name: Koehler Frank 13-27
Location ID: 322556



Photo 2. Ground photo of the tank battery and well pad field. Photo shows that the crop has been harvested and will need to be re-inspected during the next growing season.