

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA-67S96W /2NWNW

Location ID: 324175



Photo #5090 from entrance to location.



Photo #5091 Bird protectors missing on separator burners.