

Caerus Piceance LLC
Freedom Unit 197-33B
Location # 336007



Location



location

Caerus Piceance LLC
Freedom Unit 197-33B
Location # 336007



Debris



Debris

Caerus Piceance LLC
Freedom Unit 197-33B
Location # 336007



Debris



Cut slope shows signs of lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Caerus Piceance LLC
Freedom Unit 197-33B
Location # 336007**



Cut slope shows signs of lack of stabilization



Cut slope shows signs of lack of stabilization



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources