

# Inspection Photos

10/18/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 336038

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 336038



**Photo 1:** Photos taken from the interim areas of the Location. Photo shows interim areas are predominantly undesirable plant species; weeds appear to be hindering the reclamation as little to know desirable plant germination and establishment was observed.

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 336038



**Photo 2:** Photos taken from the interim areas of the Location. Photo shows interim areas are predominantly undesirable plant species; weeds appear to be hindering the reclamation as little to know desirable plant germination and establishment was observed.

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 336038



**Photo 3:** Photos show anchor on the west wend of the Location without an appropriate visible marker that can be easily seen. Photo on the left taken ~6-8 feet from the marker (yellow arrow); photo also shows anchor on the east end of the Location (red) that has been appropriately marked and can be easily seen.