

# Inspection Photos

10/18/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335537

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 335537



**Photo 1:** Photos taken from the west end of the Location. Photo shows outlet has not been constructed in accordance with good engineering practices to allow for proper stormwater discharge from the Location. Erosion degradation at outlet evident; stormwater discharge causing degradation and sediment deposition on offsite areas.





Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 335537



**Photo 2:** Photo shows erosion degradation and sediment deposition occurring offsite due to improper stormwater discharge from the Location.



## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 335537



**Photo 3:** Photo provides example of interim areas; interim areas are progressing towards 1003 standards.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850  
Location ID: 335537



**Photo 4:** Photo shows peeling label at the tank

