

Inspection Photos
Location Name: Esterling 44-33H-6-61
Location ID: 428695



Photo 1 – Pumping Unit




Photo 2 – Wellhead



Inspection Photos
Location Name: Esterling 44-33H-6-61
Location ID: 428695




Photo 3 – Unmarked Riser



Photo 4 – Flare and ECD

Inspection Photos
Location Name: Esterling 44-33H-6-61
Location ID: 428695



Photo 5 – Separators




Photo 6 – Unmarked Riser



Inspection Photos
Location Name: Esterling 44-33H-6-61
Location ID: 428695



Photo 7 – VRU



Photo 8 – Tank Battery



Inspection Photos
Location Name: Esterling 44-33H-6-61
Location ID: 428695



Photo 9 – Tank Battery Sign

