

Inspection Photos
Location Name: Rollie J Vincent A # 1
Location ID: 332911



Photo 1 WH sign

Photo 2 WH

Inspection Photos

Location Name: Rollie J Vincent A # 1
Location ID: 332911




Photo 3 Card in meter house indicates calibration is not current (front)



Photo 4 Gas Meter Run

Inspection Photos
Location Name: Rollie J Vincent A # 1
Location ID: 332911




Photo 5 Card in meter house indicates calibration is not current (back)