

Nessu Consolidation Spill

June 2021 Aerial Image

Outline of disturbed/compacted soils



outline of disturbed and compacted soils at remediation project 15797. Disturbed area approximately 0.37 acres

12307763



200 ft