

Final Reclamation Inspection

October 7th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 330553

Inspection Document #: 701900169

Weld County, CO

SWSW Section 13 T5N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Shupe 13-33
Location ID: 330553




Photo 1. 2018 aerial imagery of the well pad (North is up). The tank battery (highlighted in blue) remains active for the producing well API # 123-19455.

Inspection Photos
Location Name:Shupe 13-33
Location ID: 330553



Photo 2. Overview photo of the well pad taken at ground level from west of the well pad. Note: well pad lies within a sod grass field.

Inspection Photos
Location Name:Shupe 13-33
Location ID: 330553



Photo 3. Photos taken from the middle of the well pad. Left photo facing north and right photo facing east.

Inspection Photos
Location Name:Shupe 13-33
Location ID: 330553



Photo 4. Photos taken from the middle of the tank battery. Left photo facing south and right photo facing west. Photos show that the well pad appears consistent with the reference area (see photo 5).

Inspection Photos
Location Name:Shupe 13-33
Location ID: 330553



Photo 5. Reference photo northeast of the well pad.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number:
701900169