

Final Reclamation Inspection

October 7th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 330982

Inspection Document #: 701900170

Weld County, CO

SENW Section 2 T4N R67W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Kathlyn 1
Location ID: 330982



Photo 1. 2014 aerial imagery of the well pad, tank battery, reference area and access road (north is up).

Inspection Photos
Location Name:Kathlyn 1
Location ID: 330982



Photo 2. Overview photo of the well pad taken at ground level from west of the well pad. Note: well pad lies within a winter wheat field.

Inspection Photos
Location Name:Kathlyn 1
Location ID: 330982



Photo 3. Photos taken from the middle of the well pad. Left photo facing north and right photo facing east.

Inspection Photos
Location Name:Kathlyn 1
Location ID: 330982



Photo 4. Photos taken from the middle of the tank battery. Left photo facing south and right photo facing west. Photos show that the well pad appears consistent with the reference area (see photo 5).

Inspection Photos
Location Name:Kathlyn 1
Location ID: 330982



Photo 5. Reference photo north of the well pad.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number:
701900170

Inspection Photos
Location Name:Kathlyn 1
Location ID: 330982



Photo 6. Overview photo of the tank battery taken at ground level from the northern edge. Note: Gravel remains at the tank battery and large patches of kochia and musk thistle were observed on the southern edge (see photo 7).

Inspection Photos
Location Name:Kathlyn 1
Location ID: 330982



Photo 7. Patch of musk thistle at southern edge of the tank battery.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number:
701900170