

Inspection Photos

Operator: BP America
API: 067-05000
Date: 10/22/2021



Photo 1. View of the project area from the western edge facing center. Revegetation is progressing within portions of the project area.



Photo 2. View of the plugged well parker facing northwestward. Dense musk thistles in post flowering and rosette condition, observed within the project area.



Photo 3. View of more dense musk thistles in the project area. Approximately 2000 individuals observed.



Photo 4. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing here with sideoats grama, western wheatgrass, James galleta, and rubber rabbitbrush.



Photo 5. View of the reference area comprised of pinyon and juniper woodland with understory of sagebrush, James galleta, sandbergbluegrass, and prickly pear.