

Inspection Photos  
Operator: Simcoe  
API: 067-06298  
Date: 10/22/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern pfill slope from the northeastern corner facing westward. Revegetation is progressing with western wheatgrass, sand dropseed, and rubber rabbitbrush.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of the reference area comprised of pinyon and juniper woodland with understory of sagebrush, James galleta, sandbergbluegrass, and prickly pear.