

Inspection Photos
Operator: Simcoe
API: 067-05274
Date: 10/22/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of materials and debris stored in the northwestern corner of the well pad.



Photo 3. View of the northern fill slope from the northwestern corner facing eastward.



Photo 4. View of the reference area comprised of irrigated grass field with grasses such as smooth brome, orchard grass, and foxtail barley, as well as scattered sagebrush and wetland vegetation such as cattails.