

Caerus Piceance LLC
PCU T35X-11G
Location # 335712



Location



location



Caerus Piceance LLC
PCU T35X-11G
Location # 335712



Location



Location/lack of battery signage



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Piceance LLC
PCU T35X-11G
Location # 335712



Location



location/tank labels are still XTO



Caerus Piceance LLC
PCU T35X-11G
Location # 335712



Debris



Debris



Caerus Piceance LLC
PCU T35X-11G
Location # 335712



Lack of stabilization/erosion/sediment migration



Lack of stabilization/erosion/sediment migration



Caerus Piceance LLC
PCU T35X-11G
Location # 335712



Lack of stabilization/erosion/sediment migration



Lack of stabilization/erosion/sediment migration

