

Caerus Piceance LLC
PCU T87X-3G
Location # 335796



Location



location



Caerus Piceance LLC
PCU T87X-3G
Location # 335796



Location/lack of battery signage



location

Caerus Piceance LLC
PCU T87X-3G
Location # 335796



Location



location/labeling on tank is still XTO



Caerus Piceance LLC
PCU T87X-3G
Location # 335796



Debris



Lack of stabilization/erosion



Caerus Piceance LLC
PCU T87X-3G
Location # 335796



Lack of stabilization/erosion



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources