

Inspection Photos

API: 125-06935

Operator: PETRON DEVELOPMENT COMPANY

Inspection Date: 10/25/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 125-06935 | Date: 10/25/2021

Inspection Photos



Photo 1. Facing east at the well site. This area at the well site has insufficient Corn crop cover and consists of undesirable grass (Barnyard grass). This area was measured to be 25 ft.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06935 | Date: 10/25/2021

Inspection Photos



Photo 2. Facing south at the well site. This area at the well site has insufficient Corn crop cover and consists of undesirable grass (Barnyard grass). This area was measured to be 26 ft.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06935 | Date: 10/25/2021

Inspection Photos



Photo 3&4. The photo on the left shows the insufficient crop cover (corn) and the undesirable grass growth (Barnyard grass). The photo on the right shows the Corn crop cover. Quadrat was placed to show vegetation in this area (1m).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06935 | Date: 10/25/2021

Inspection Photos



Photo 5. Facing east toward the surrounding undisturbed crop which has uniform crop cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06935 | Date: 10/25/2021

Inspection Photos



Photo 6. Aerial image shows the area at the well site which has insufficient crop cover shown by the light area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-06935 | Date: 10/25/2021