

Inspection Photos

API: 125-12071

Operator: PETRON DEVELOPMENT COMPANY

Inspection Date: 10/25/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 125-12071 | Date: 10/25/2021

Inspection Photos



Photo 1. Drone aerial photo facing west at the abandoned site. No evidence of surface disturbance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-12071 | Date: 10/25/2021

Inspection Photos



Photo 2. Drone aerial photo facing east at the abandoned site. No evidence of surface disturbance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 125-12071 | Date: 10/25/2021