

Inspection Photos

Location Name: Champlin 67 AMOCO G 1


Location ID: 319913

Oct 21, 2021 at 1:23:56 PM
COGCC



Pic 1 Wellhead weeds unmanaged

Oct 21, 2021 at 1:25:48 PM
39.850697,-104.465350
Bennett CO 80102
United States
COGCC



Pic 2 Separator, and gas meter run

Inspection Photos

Location Name: Champlin 67 AMOCO G 1

Location ID: 319913

Oct 21, 2021 at 1:27:53 PM
39.850800,-104.485327
COGCC



Pic 3 tank, weeds unmanaged



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources