

Inspection Photos

Location Name: UPRR-Wailes 1-1

Location ID: 319742

Oct 22, 2021 at 1:41:51 PM
39.899705,-104.393533
1721 E 112th Ave
Bennett CO 80102
United States
COGCC



Oct 22, 2021 at 1:41:59 PM
39.899705,-104.393533
1721 E 112th Ave
Bennett CO 80102
United States
COGCC



Pic 1 separator

Pic 2 tank

Inspection Photos

Location Name: UPRR-Wailes 1-1

Location ID: 319742



Pic 3 tank, berm needs to be rebuilt



Pic 4 wellhead, weeds unmanaged, sign needs to be placed back on well.

Inspection Photos
Location Name: UPRR-Wailes 1-1
Location ID: 319742

Oct 22, 2021 at 1:44:07 PM
39.899600,-104.393581
1721 E 112th Ave
Bennett CO 80102
United States
COGCC



Pic 5 trash and debris inside fencing.