

# Final Reclamation Inspection

October 25, 2021

Operator: MACHII-ROSS PETROLEUM CO - 52250

Location ID: 406103

Inspection Document #: 697503425

Weld County, CO

SWSE Section 32 T2N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HALEY #2  
Location ID: 406103




**Photo 1.** Photo taken from the well location on 5/26/2021, facing South. Photo illustrates the Operator has failed to remove all equipment.



**Photo 2.** Photo taken from the well location on 5/26/2021, facing Northwest. Photo illustrates other areas surrounding the well location appear to meet Rule 1004 vegetative standards.



Inspection Photos  
Location Name: HALEY #2  
Location ID: 406103



**Photo 3.** Photo taken from the well location on 5/26/2021, facing Northeast. See comments under Photo 2.



**Photo 4.** Photo taken from the well location on 5/26/2021, facing South. Photo illustrates the access road appears reflective of reference crop areas.

Inspection Photos  
Location Name: HALEY #2  
Location ID: 406103



**Photo 5.** Photo taken from the removal work conducted on 12/22/2020.



**Photo 6.** Photo taken from the removal work conducted on 12/22/2020.

Inspection Photos  
Location Name: HALEY #2  
Location ID: 406103



**Photo 7.** Photo taken from the removal work conducted on 12/22/2020.



**Photo 8.** Photo taken from the removal work conducted on 12/22/2020.

Inspection Photos  
Location Name: HALEY #2  
Location ID: 406103



**Photo 9.** Photo taken from the well location, facing West. Photo confirms that all equipment has been removed.

