

# Final Reclamation Inspection

October 25, 2021

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 320313

Inspection Document #: 697503430

Adams County, CO

NWSW Section 12 T1S R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: NORTH YORK #13-12-3

Location ID: 320313



**Photo 1.** Photo taken from the eastern location, facing West. Photo illustrates Operator has failed to complete final reclamation activities.



Inspection Photos  
Location Name: NORTH YORK #13-12-3  
Location ID: 320313



**Photo 2.** Photo taken from the meter house location, facing South. Photo illustrates the meter house has been removed.



**Photo 3.** Photo taken from the meter house location, facing East. Photo illustrates a gravel pile and some wire debris.

Inspection Photos  
Location Name: NORTH YORK #13-12-3  
Location ID: 320313



**Photo 4.** Photo taken from the eastern well location access road, facing West. See comments under Photo 1.



**Photo 5.** Reference photo taken east of location, facing South. See comments under Photo 1.