

Inspection Photos

Location Name: CAERUS PICEANCE LLC Gardner Federal /28-1 (PC-28),

Location ID: 311692



Photo #5105 from entrance to location.



Photo #5106 from entrance to location.



Inspection Photos

Location Name: CAERUS PICEANCE LLC Gardner Federal /28-1 (PC-28),

Location ID: 311692



Photo #5107 No battery sign located at the tank battery.



Photo #4027 from inspection #699803233 conducted on 6/11/21.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC Gardner Federal /28-1 (PC-28),

Location ID: 311692



Photo #5108 Glycol storage tank missing required information.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources