

## Inspection Photos

**Location Name: CAERUS PICEANCE LLC S.PARACHUTE TBI-67S96W /36SENE**

**Location ID: 324250**



**Photo #5139 from entrance to location.**



**Photo #5140 from entrance to location.**

## Inspection Photos

**Location Name: CAERUS PICEANCE LLC S.PARACHUTE TBI-67S96W /36SENE**

**Location ID: 324250**



**Photo #5141 No tank battery sign located at the tank battery.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources