

Inspection Photos
Location Name:UPRR 23 Pan Am B2
Location ID:319928



Photo #1 Tanks.

Photo #2 Meter run & Separator.

Inspection Photos
Location Name:UPRR 23 Pan Am B2
Location ID:319928



Photo #3 Well Head.



Photo #4 Stained soil around vault.