

Inspection Photos

10/25/2021

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 311604

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311604



Photo 1: Photos show control measures to stabilize the production areas of the Location, and to mitigate tracking and offsite sediment transport have not been maintained in proper functioning condition, and are now inadequate.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC # 10456
Location ID: 311604



Photo 2: Photos show control measures to stabilize the production areas of the Location, and to mitigate tracking and offsite sediment transport have not been maintained in proper functioning condition, and are now inadequate.