

Inspection Photos
Location Name: Carl R. Deepe C #2
Location ID: 318388



Photo 1 Weeds along access rd. have been cut

Photo 2 WH sign

Inspection Photos
Location Name: Carl R. Deepe C #2
Location ID: 318388



Photo 3 WH

Photo 4 Pump Jack, weeds have been cut around location and equipment

Inspection Photos
Location Name: Carl R. Deepe C #2
Location ID: 318388



Photo 5 ancillary equipment