

Inspection Photos

10/25/2021

Operator: TEP ROCKY MOUNTAIN LLC #
96850

Location ID: 323866
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location ID: 323866



Photo 1: Photo shows that Operator has placed a board into the containment BMPs; control measures to prevent wildlife access to the containment BMP remains inadequate.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location ID: 323866



October 25, 2021
39.4590102N 107.83286717W



October 25, 2021
39.45906696N 107.83290445W

Photo 2: Photo taken from the stormwater diversion ditch on the west end of the Location, facing north. Photo shows that the stormwater diversion ditch remains improperly constructed with an appropriate outlet to prevent offsite degradation due to runorr.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location ID: 323866



Photo 3: Photos taken north of the ditch. Photo shows offsite erosion degradation due to improper stormwater runoff controls on the Location.